


# styropan

## SAFE USE INSTRUCTIONS

### OF POLYSTYRENE CUTTING MACHINES



It is important to read the following safe use instructions carefully and to their entirety:



The unit operator should be trained and familiar with the device. During the unit operation, the appropriate personal protective equipment should be used, and all required measures must be taken when performing a heating task.



The unit can be operated exclusively with the original cables supplied with the purchased product. Any use of other cables can lead to destruction of the adapter or to increased risk of fire and other damages.



The unit should be used in exterior or properly ventilated areas.



The device operates using a low voltage adapter connected to a 220V power supply. It is therefore important to protect the device from humidity. The operation during rain or other humid conditions forbidden! In case faults must be repaired, please disconnect the device from the power supply! Repairs should be performed exclusively by authorized technicians.



The wire is very hot during the cutting procedure and it should not be come into contact in any way. This would lead to serious burns. Therefore, it is recommended to use the appropriate protective gloves.



Furthermore, the wire is under high tension. During operation, there is the possibility that the wire is cut, and a spark is created. Consequently, the use of safety glasses is mandatory!



Before work commences, all screws must be securely tightened, and the outputs must be properly connected.



Before use, you must ensure the stable placement and remove of potential hazardous sources from the work area.



If the wire is not heated after prolonged use, the adapter may have been overheated and it should be left to cool.



The button must not be continuously pressed! (risk of fire).